

Historic Tax Credits 101





Jenny Parker Architectural Historian National Park Service


Senior Preservation Architect North Carolina State Historic Preservation Office


Federal Tax Incentives


 $10^0 / 0 \ \ \, {\rm Tax\ credit\ for\ the\ rehabilitation\ of\ older\ non-historic\ buildings}$

Tax credit for the "certified rehabilitation" 20% Tax credit for the certified historic structures"


Easements Donation of specified property rights to protect a historic structure or site in exchange for tax benefits







Background



In 1976 Congress created federal tax incentives to promote historic preservation and community revitalization.

20% Credit since 1976: \$73 Billion invested 40,300+ projects

Federal Rehabilitation Tax Credit

Rehabilitation is "...the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historic character."



What is a tax credit?

• A tax credit is a dollar-fordollar reduction in the amount of taxes you owe



• The credit = 20% of qualifying rehabilitation costs





3

Rehabilitation Tax Credit Basics

Three questions determine if a project is eligible:

1. Does the property contain a historic building?

- 2. Will the rehabilitation be substantial?
- 3. Will it be used for an income-producing purpose?



Project Eligibility: "certified historic structure"

Does the property contain a historic building?

Historic – listed in the National Register of Historic Places or within a certified local historic district

Building - as defined by Dept. of Treasury regulations, "any structure or edifice enclosing a space within its walls, and usually covered by a roof, the purpose of which is, to provide shelter or housing, or to provide working, office, parking, display, or sales space."



Project Eligibility

Will the rehabilitation be substantial?

The cost of the project must exceed the greater of \$5,000 or the property's adjusted basis used for tax purposes.

- A B C + D = adjusted basis
- A= purchase price of the property
- **B**= value of the land at the time of purchase
- C= depreciated taken for tax purposes
- D= cost of capital improvements

Adjusted Basis

Mr. Smith has owned his property for 15 years Purchased for \$150,000

- of that, \$40,000 was attributed to land
- In the past 15 years the property has been depreciated for tax purposes a total of \$60,000

Improvements have cost \$8,000

150,000-40,000-60,000+8,000= 58,000 (adjusted basis)

Mr. Smith must spend at least \$58,000 on the rehabilitation to qualify for the tax credits.

Project Eligibility

Will it be used for an income-producing purpose?

The property must be used for an income producing purpose- it cannot be your personal residence.


Some acceptable uses include: commercial, industrial, agricultural, rental residential




<section-header>

Secretary of the Interior's Standards for Rehabilitation

- Apply to all properties; no matter the building type, age, size, use, or material
- Apply to exteriors AND interiors
- Apply to the building site and environment, landscape, attached and adjacent new construction
- All 10 Standards must be met to receive certification









Submission Requirements

- Everything must be in duplicate

 Forms, photographs, plans, maps, etc.
- The 3 parts must be submitted in order
- All material is submitted to the SHPO first
- Cover sheets must exactly match the most recent published version

Timing of Review

- Both the SHPO and NPS have a 30-day review limit
- Projects will be put on hold if all the necessary information is not included- this lengthens the review process
- Fees associated with Parts 2 and 3 review, must be paid before review can begin





Part 1 - Evaluation of Significance

Owner requests determination by NPS that a property contains a "certified historic structure"


- Contributes to the significance of a National Register or certified local historic district
- Listed individually in the National Register (If only one building exists on property, then Part 1 may be omitted.)
- Preliminary determination of eligibility











Part 1: Submission


Applicant must submit:

- description of physical appearance
- Statement of significance
- Photographs of property (exterior & interior)
- Historic district map and site plan



powers and the country, and endowed out powers in the region of an early 20° century rathe bars in this region.


Example of a Part 1 application





Part 2 - Description of Rehabilitation

- Applicant describes condition of property prior to rehabilitation and proposed work
- Every major building feature should be described
- Photographs document ALL areas of property even where no work is planned
- Floor plans and elevation drawings should reflect existing condition and proposed work
- Proposed work is evaluated based upon the Secretary of the Interior's Standards for Rehabilitation



Part 2 Form: Example

HISTORIC PRESERVATION CERTIFICATION APPLICATION PART 2 - DESCRIPTION OF REHABILITATION

PART 2 - DESCRIPTION OF REHABILITATION unty name <u>Houseal Building</u> Art Population unty same <u>316 Main Street</u>, City, State


 Debide backglobe of vielastBMD and Augusta to page an event a source a set or ansi sources for a his horizon before the sources and and an event and an event and a set of the source and a source a set of the sources menter of sources and an event and an event and an event and a source a set of the sources and an event an event and an event an event an event an e

The building is constructed of red brick. It has been painted white sometime after the period of significance for the district. There is some brick spaling and a number of degraded mottar join The parapet cap was covered in Portland cement in a prior rehabilitation; there is some brick damage.

htts nurses 1-4_____ Drawing nurses A-1_____

beats are input in hear The part will be removed from the trick. Moleving the guidance found in Preservation Bird 1 Assessing, Calaring, and Vatan-Papeliett Treatments for Instinct Manony Buildings, using protection and appearance of the Instinct. All work will be down in accordance with the composition and appearance of the Instinct. All work will be down in accordance with the Any insplacement tracks required for regardly and the Instinct cogenaria. The PortTank cannot and top ocurre of birds will be removed; a new birds cogenariance. The PortTank be Installed.

Number 2 Feature Storefront Date of Feature 5, 1952



Part 3 - Request for Certification of Completed Work

- Owner submits completed Part 3 form along with photographs of completed work
- Project must be completed at this point (i.e. an historic commercial space must have finished walls, floor, and ceiling)
- Issued by NPS for certified historic structures where completed work meets the Standards for Rehabilitation



Keys to a Successful Project

- Contact the SHPO **EARLY** in the planning process for advice on rehabilitation treatments
- Submit **COMPLETE** application to SHPO well **BEFORE** beginning work
- Take GOOD, CLEAR photos of entire building and site BEFORE work begins
- Submit Part 2 describing **FULL** scope of work
- **DO NOT** begin work until NPS approves Part 2 application

Stay on track...

- Modify Part 2 scope of work in accordance with SHPO and NPS guidance and conditions
- Submit project amendments for review and approval before proceeding with that work
- Do not assume that local approval = certification of rehabilitation for tax credits




Leading Causes of Denials

- Insufficient pre-rehab photographic documentation
- Completing work that does not meet the Standards before contacting the SHPO or beginning the application process
- Program that is too intense for building and site
- Substantial interior demolition




Work on this three-story building was completed before the tax credit application was approved. The 1½ story rooftop addition causes the project to fail to meet the Standards.











Fire House #2 Billings, MT \$416,000







14







